

AERBIO, LTD.
320 North Walnut
Bloomington, IN 47404

Telephone: 812.334.9996

Fax: 812.334.1960

Emergency: 800.424.9300

SECTION 1: IDENTIFICATION

Product Name: Bovine Albumin Fraction V
Chemical Family: Protein
CAS No.: 9048-46-8
NFPA 704M Rating: 0-1-0
Merck Index No.: 11:207

SECTION 2: PHYSICAL DATA

Physical Data:

Appearance and Odor:	Off-white homogenous powder
Boiling point:	N/A
Vapor Pressure (mmHg):	N/A
Specific Gravity (Water=1):	N/A
Solubility in water:	Soluble
Volatility:	N/A

SECTION 3: FIRE AND EXPLOSION DATA

Fire and Explosion Information:

Flash point:	N/A
Extinguishing Media:	Water spray as in paper and wood fires
Fire Fighting Procedures:	N/A
Unusual Fire and Explosion Hazards:	N/A

SECTION 4: REACTIVITY DATA

Reactivity Data:

Stable X Unstable

Conditions to Avoid:	Hydroscopic
Hazardous Decomposition or byproducts:	None
Hazardous Polymerization:	Will not occur

SECTION 5: HEALTH HAZARD DATA

Threshold Limit Value (TLV):	Not established
Effects of Overexposure:	No immediate or long-term toxic effects in lung or other tissues.
Emergency & First Aid Procedures:	Good practice requires that bovine albumin be removed from the skin as soon as practical. Wash with soap and water.

SECTION 6: SPILLAGE AND DISPOSAL PROCEDURES

Spillage:	Sweep floors using normal solid waste cleaning equipment.
Disposal:	Incineration or landfill in accordance with local, state and federal regulations.

SECTION 7: PRECAUTION TO BE TAKEN IN HANDLING AND STORING

Other Precautions: Store in a cool, dry place. Segregate Bovine Albumin from other materials to avoid cross-contamination.

SECTION 8: SPECIAL PROTECTION INFORMATION

Ventilation: Normal industrial ventilation

Protective Gloves: Use disposable gloves

Respiratory Protection: Respirator for non-toxic down to 1 micron meeting OSHA requirements

Other Protective Equipment: Washable outer uniform recommended
